




subject to amendments



detail A

detail B

detail C

Welding points (or welding bolts) have to be made in reference to material thickness. No spots must be visible on the outer surface.

subject to amendments